





Screen reclaiming instructions for removing ink and stencil



1 Add 2 gallons of XSR-155 stencil remover to a drum of XID-480/25 ink degradable and then fill the remainder of the drum with water.




2 Apply mixed solution using a brush or spray to both sides of a screen that has had the ink scraped out. Leave for 2 minutes.



3 Pressure wash both sides with water.

4




Allow screen to dry in front of a fan.

5



Apply XHR-AN using a brush to both sides of a screen. Leave about a 10" gap from the edge of the frame.

6



Allow screen to dry in front of a fan.

7




Apply XID-480 solution using a brush or spray to both sides of a screen.

8



Pressure wash both sides with water.

9



Apply XMP- Heavy Duty Mesh Prep to both sides of the screen and rinse off with a garden hose.

SERICOL
More than ink... Solutions™

FUJIFILM

www.FujifilmSericol.com